

Swale #4, Island Way

DRAIN EASMENT CONFIRMED

PIPE RUN-01:
24" CMP, MAINTAINED BY
GOLF COURSE

REHABILITATE SWALE
BETWEEN THESE HOMES
TO ACHIEVE
UNRESTRICTED FLOW
FROM ISLAND WAY TO
PIPE RUN-01

REHABILITATE ALL
MARKED ROAD SIDE
SWALES

NOTE:
When the above improvements are being done the adjacent private driveway culverts must be cleaned. most all these culverts are badly silted up, there is always the possibility that these culverts are rusted through and will at some point need to be replaced.

18.A & 18.B

