

Swale #4, Island Way

DRAIN EASMENT CONFIRMED

PIPE RUN-01:
24" CMP, MAINTAINED BY
GOLF COURSE

REHABILITATE SWALE
BETWEEN THESE HOMES
TO ACHIEVE
UNRESTRICTED FLOW
FROM ISLAND WAY TO
PIPE RUN-01

REHABILITATE ALL
MARKED ROAD SIDE
SWALES

NOTE:

When the above improvements are being done
the adjacent private driveway culverts must be
cleaned. most all these culverts are badly silted
up, there is always the possibility that these
culverts are rusted through and will at some
point need to be replaced.

18.A & 18.B



SW Whisper Bay Dr

18

16

17

14

13

S Creek Dr

162

161

160

159

SW Bimini Cir N

11

SW Bimini Cir S

290

291

292

293

294

295

296

297

298

299

SW Harbour Bluff Pl

SW Murphy Rd

2

1

3

4

5


2

1


2

PR43- PIPE UNDER THE ROADWAY





Swale 34, 4842 SW Bimini Circle N



Evergreen

4396 SW Bimin Cir S

Legend

